## Flat Washers

### Phosphor Bronze

| Thread Size | Weight per 100 kg | Pack Quantity | Part Number |
|---|---|---|---|
| M6 | 0.05 | 100 | OWP 06 |
| M8 | 0.15 | | OWP 08 |
| M10 | 0.25 | | OWP 10 |
| M12 | 0.50 | | OWP 12 |

**Material:** Phosphor Bronze.

### Brass

| Thread Size | Weight per 100 kg | Pack Quantity | Part Number |
|---|---|---|---|
| M6 | 0.05 | 100 | OWB 06 |
| M8 | 0.15 | | OWB 08 |
| M10 | 0.25 | | OWB 10 |
| M12 | 0.50 | | OWB 12 |

**Material:** Brass.

### Stainless Steel

| Thread Size | Weight per 100 kg | Pack Quantity | Part Number |
|---|---|---|---|
| M6 | 0.05 | 100 | OWS 06 |
| M8 | 0.15 | | OWS 08 |
| M10 | 0.25 | | OWS 10 |
| M12 | 0.50 | | OWS 12 |

**Material:** Stainless Steel.

## Spring Washers

### Phosphor Bronze

| Thread Size | Weight per 100 kg | Pack Quantity | Part Number |
|---|---|---|---|
| M6 | 0.04 | 100 | OTP 06 |
| M8 | 0.10 | | OTP 08 |
| M10 | 0.20 | | OTP 10 |
| M12 | 0.50 | | OTP 12 |

**Material:** Phosphor Bronze.

### Stainless Steel

| Thread Size | Weight per 100 kg | Pack Quantity | Part Number |
|---|---|---|---|
| M6 | 0.04 | 100 | OTS 06 |
| M8 | 0.10 | | OTS 08 |
| M10 | 0.20 | | OTS 10 |
| M12 | 0.50 | | OTS 12 |

**Material:** Stainless Steel.